

Phone: (604) 888-3084 Toll Free: 1-800-201-8822 Fax: (604) 888-7754 Toll Free: 1-800-708-9888

ISO 9001 Registered Quality System QMI Certificate # 004008 Bu

Burlington, Ontario, Canada

## No Clean Super Wick Cat. No. 400NS Series

## Product Description



Any place you put solder in, you can take it out with Super Wick. Remove the most expensive circuitry with confidence. Super Wick is pure copper, specially wounded in static free bobbins.

- NO CLEAN type flux
- Static Free Bobbins
- Meets MIL-F-14256F (ansi/j-std-0004)
- RoHS Compliant

## **Application Tips**

Just lay the Super Wick on the soldered join, apply tip of soldering iron to top side till solder melts, and lift iron and Super Wick together to leave a clean connection ready for component removal or replacement.

## Availability

No Clean Super Wick					
Length	0.025" #1 White	0.05" #2 Yellow	0.075" #3 Green	0.1" #4 Blue	0.125" #5 Brown
5 ft	-	424-NS	425-NS	426-NS	-
50 ft	-	453-NS	-	454-NS	-

Note:

This information is believed to be accurate. It is intended for professional end users having the skills to evaluate and use the data properly. M.G. Chemicals Ltd. Does not guarantee the accuracy of the data and assumes no liability in connection with damages incurred while using it.